

I SALI DELLA VITA MgKI

BIOSTAB

GRANULES

ACTIVATOR SPECIFICALLY FOR SALINE ELECTROLYSIS SYSTEMS. INCREASES THE PRODUCTION OF CHLORINE IN SALT STERILISERS. REDUCES THE FORMATION OF LIMESCALE DEPOSITS ON ELECTRODES, ENCOURAGING AND STABILISING THE PRODUCTION OF CHLORINE IN THE SWIMMING POOL.

CHARACTERISTICS:

BIOSTAB INCREASES THE PRODUCTION OF CHLORINE IN SALT STERILISERS. REDUCES THE FORMATION OF LIMESCALE DEPOSITS ON ELECTRODES, ENCOURAGING AND STABILISING THE PRODUCTION OF CHLORINE IN THE SWIMMING POOL. THE PARTICULAR FORMULA PROTECTS THE ELECTRODE FROM THE EFFECTS OF SCALING.

USE AND DOSES:

INITIAL FILLING OF THE SWIMMING POOL:

25 – 50 GRAMS OF BIOSTAB PER CUBIC METRE OF WATER

MAINTENANCE DOSES:

CHECK THE CONTENT OF HYDROGEN CYANIDE IN THE WATER ON A MONTHLY BASIS AND ADD AS MUCH BIOSTAB AS IS NEEDED TO MAINTAIN THE CONTENT OF THE STABILISER BETWEEN 25 AND 50 ppm

PHYSICAL AND CHEMICAL CHARACTERISTICS

APPEARANCE WHITE POWDER
ODOUR ODOURLESS
FULLY DISSOLVABLE IN WATER
APPARENT SPECIFIC WEIGHT AT 1.15 - 1.25 Kg/l

LEGAL REFERENCES

PRODUCT CONFORMS TO THE AGREEMENT PROTOCOL BETWEEN STATE AND REGIONS FROM 16 JANUARY 2003

WARNINGS AND POSSIBLE RISKS

P102: KEEP OUT OF CHILDREN'S REACH

EXPOSURE CHECK/ INDIVIDUAL PROTECTION

BREATHING PROTECTION:
NOT REQUIRED
HAND PROTECTION: GLOVES
EYE PROTECTION: SAFETY GOGGLES
BODY PROTECTION: PROTECTIVE CLOTHING
ADDITIONAL MEASURES: BOTTLES FOR EYE RINSING
TLV LIMITS: NOT GIVEN

SPECIAL PROTECTION IS NOT NEEDED

HANDLING AND STORAGE

USE RUBBER GLOVES AND SAFETY GOGGLES WHEN HANDLING

STORE AT ROOM TEMPERATURE AND AWAY FROM DIRECT SUNLIGHT.

FIRST AID MEASURES

SKIN: WASH THOROUGHLY UNDER RUNNING WATER
EYES: IMMEDIATELY AND THOROUGHLY WASH WITH RUNNING WATER KEEPING EYELIDS OPEN. IF NECESSARY, SEEK SPECIALIST MEDICAL HELP
SWALLOWING: THOROUGHLY RINSE MOUTH AND DRINK WATER.
SEE A DOCTOR AS SOON AS POSSIBLE.

VAPOUR INHALATION: NOT APPLICABLE

COMPOSITION:

CONTAINS ANTI-SCALE AND CHLORINE STABILISER

PACKAGING

5 KG BUCKET

TRANSPORT INFORMATION

ROAD TRANSPORT:
PRODUCT NOT CLASSIFIED AS DANGEROUS FOR TRANSPORT.